


HAM6 GS13s, shaker on HAM6 blue beam, 700-900 Hz injection, BLACK: no shaking




\*T0=10/05/2015 02:30:30

\*Avg=10/Bin=3

BW=0.374998

DARM during HAM6 shaking, BLACK: no shaking




\*T0=10/05/2015 02:30:30

\*Avg=10/Bin=3

BW=0.374998

Accel. near suspension, taps on ISI suspension wire loc. 3, BLUE: damping clamp on wire, RED: no clamp, all blue traces in front of red



\*T0=06/01/1980 00:00:00

\*Avg=1/Bin=10

\*BW=0