

Figure 3. View from ETMY beam spot, before and after stray light upgrade, with optical lever beam and reflections from gate valve (at center), blacked out

