


IO path on the PSL needs to be aligned


Cheryl Vorvick

14 Oct 2019


Something new on EOM steering mirror




Different angle, EOM steering mirror



Fringe pattern, there should be a round beam #1




Fringe pattern, there should be a round beam #2



Fringes, beam on MAIN BEAM Wedge mount, pickoff for EOM power DCPD

Light where there should be none #1




Thin Film Polarizer Frame, IO High Power Beam Dump,
there should be little to no light, and what light there might be should be diffuse

Light where there should be none #2



Light where there should be none #3



Reflection from L2 clipped on WG1, WG1 light

