IR photos

Alignment that maximizes current on PD, my guess is that the spot is a ghost beam - if it were the main beam it should be centered on PD



Pitch down to reduce current



Yaw to left of optimal yaw, I think the ghost beam has dropped into the hidden side of the PD recess



Pitched up higher than optimal with current matched to pitch down photo



Yaw even further left, spot may be main beam starting to fall off diode. We lost lock before being able to yaw in the other direction







