
04/24/14 - Update LHO Safe.snap with correct ..._THRESH_MAX values

h1hpibs_safe.snap

H1:HPI-BS_WD_L4C_THRESH_MAX 1 8.025000000000000e+04
→ 3.000000000000000e+04

h1hpietmx_safe.snap

H1:HPI-ETMX_WD_L4C_THRESH_MAX 1 8.023400000000000e+04
→ 3.000000000000000e+04

h1hpietmy_safe.snap

H1:HPI-ETMY_WD_L4C_THRESH_MAX 1 8.023100000000000e+04
→ 3.000000000000000e+04

h1hpiitmz_safe.snap

H1:HPI-ITMX_WD_L4C_THRESH_MAX 1 8.024500000000000e+04
→ 3.000000000000000e+04

h1hpiitmy_safe.snap

H1:HPI-ITMY_WD_L4C_THRESH_MAX 1 8.024000000000000e+04
→ 3.000000000000000e+04

h1hpiham1_safe.snap - was ok

H1:HPI-HAM1_WD_L4C_THRESH_MAX 1 3.000000000000000e+04

h1hpiham2_safe.snap

H1:HPI-HAM2_WD_L4C_THRESH_MAX 1 8.033100000000000e+04
→ H1:HPI-HAM2_WD_L4C_THRESH_MAX 1 3.000000000000000e+04

h1hpiham3_safe.snap

H1:HPI-HAM3_WD_L4C_THRESH_MAX 1 8.032900000000000e+04
→ 3.000000000000000e+04

h1hpiham4_safe.snap - was ok

H1:HPI-HAM4_WD_L4C_THRESH_MAX 1 3.000000000000000e+04

h1hpiham5_safe.snap - was ok

H1:HPI-HAM5_WD_L4C_THRESH_MAX 1 3.000000000000000e+04

h1hpiham6_safe.snap - was ok

H1:HPI-HAM6_WD_L4C_THRESH_MAX 1 3.000000000000000e+04

controls@opsws2:h1 o\$ svn commit -m "fixed ...L4C_THRESH_MAX values.
h1hpiham5_safe.snap already had modifications pending for commit" burtfiles/

Sending burtfiles/h1hpibs_safe.snap
Sending burtfiles/h1hpietmx_safe.snap
Sending burtfiles/h1hpietmy_safe.snap
Sending burtfiles/h1hpiham2_safe.snap
Sending burtfiles/h1hpiham3_safe.snap
Sending burtfiles/h1hpiham5_safe.snap
Sending burtfiles/h1hpiitmx_safe.snap
Sending burtfiles/h1hpiitmy_safe.snap

Transmitting file data

Committed revision 7796.