




Watchdogs Trip Summary

Almost all the trips have been caused by human intervention
(maintenance, commissioning, switching gains, etc.)


Two trips are worth mentioning

Platform	Trip time	What Tripped	Cause	Log
ISI-ETMY	1083081670 (Local: Friday May 02, 09:00:54)	Drive	Optics reinjection?	
ISI-ETMX	1083143781 (Local: Saturday May 03 02:16:05)	Drive	Activity in the LVEA? SUS measurement?	Sheila's post (11700)




Data Display start at 14-05-03-09-16-04 (10 seconds)


Ch 3: H1:HPI-ETMX_LACINF_H2_IN1_DQ



Ch 6: H1:ISI-ETMX_ST1_BLND_X_MIXSTATE




Ch 2: H1:ISI-ETMX_ST2_GS13INF_H2_IN1_DQ



Ch 5: H1:ISI-ETMX_ST1_MASTER_H2_DRIVE_DQ



Ch 1: H1:ISI-ETMX_ST1_T240INF_X1_IN1_DQ



Ch 4: H1:HPI-ETMX_STSINF_B_X_IN1_DQ

