





Fiber Guard – open on the inside so screw likely bounced down to top of test mass and then into fibers from the inside.

We're not sure how exactly it fell down to the test mass, possibly between the PUM and PenRe, or around the side of them and then bounced off the structure and back into the optic area.