



adjusting the position of the feedthrough to make sure that this driven-shield could not get in contact with the test stand



bolting the ADE boxes together to make sure that they share the same ground





ground the ADE boxes to the test stand

