

10 Sept 2012 HAM 1

	1	2	3	4	} checked
V	468	253	439	471	
T	721	746	177	720	
L			525	505	

T Coal 700 721 201 700


Y<sup>coord</sup> -3050.7 - set up SETIX for Horiz shot

$-3050.7 \text{ mm} - 23.25'' = -2460.15 \text{ mm}$

DIST 2460 mm

$\angle 0.2 \text{ mm}$  ← CLOSE  
 $\angle 0.1 \text{ mm}$  ← FAR

+ 14"  
- 2"



$\tan \theta = \frac{\text{OPP}}{\text{ADJ}}$

BS	HI	FS	ELEV	DESC
-847.7 mm	846.7		1.0 mm	#503 WEST WALL SOUTH BAY
		-0.722	} found Rod not ground	NE
		0.719		SE
		0.720		SW
		0.721		NW
		0.619		
		0.729	-865.2	NW } Cut over
		0.729	-865.2	NE } on Support Table
		0.727	-865.2	SE
		0.728	-865.2	SW
		+847.7 mm		BENCH


-833.7 mm

1.0

#503

-1.179"  
-1.179"  
-1.177"

NW } Support Table  
SW } above cutout  
E }



+833.7

BENCH

1 2 3

4