

IO_MB_M3, VIEW 2:

Replaced in the main IFO beam 15 Jan 2019 due to excessive scattering,
6 small dings in an arc found on the front surface



