



Repeats of impulse injections. Compare to the figure on the top right (from before the septum window replacement). The delays and amplitude consistency still point to the septum (though not necessarily the septum window).


Figure 2a. H1 coupling time and amplitude consistent with septum, not HAM5/6 walls or ISI tables




Repeat, HAM6 end cap



Repeat, +Y flange





Resonance structure in DARM from impulse injections still seems to match structure in septum accelerometer better than other accelerometers

