





In its original position, the baffle was very close to hitting the eddy damper. With the new dampers, I adjusted the baffle to give an extra mm or so of clearance, shown here.

Spots produced by a flashlight shining on Al foil used to observe the $\sim 4\text{Hz}$ modes. It was my impression that the 4Hz resonances were bending modes of the outer ring.

