

Coherence between grounding current monitors and DARM, no injections

Dark Blue: clamp on grounding cable, Light Blue: magnetometer attached to BSC3, Red: rack magnetometer

Current bias settings: ITMX -428V, ITMY -428V

Proposed bias settings: ITMX 0V, ITMY 60V

