

Result

Legend
Cursor

Param
Config

7

solid 2
Circle 1.0
solid 0.10


Legend
Cursor

Param
Config



7

solid 2
Circle 1.0
solid 0.10

Transfer function: black = 6Aug2018, blue = 21Apr2020, red = 18Sep2021



Transfer function



Zoom

Active

New

Options...

Import...


Export...

Reference...

Calibration...

Print...

Transfer function




*T0=21/01/2024 03:09:48

*Avg=5

*BW=0.046875

Transfer function




*T0=21/01/2024 03:09:48

*Avg=5

*BW=0.046875

Coherence



*T0=21/01/2024 03:09:48

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...


Print...

Pause


Resume

Abort


Transfer function: black = 6Aug2018, blue = 19Sep2019, red = 21Apr2020



Transfer function



Coherence



Active

New

Options...

Import...

Export...

Reference...

Calibration...


Print...

Pause

Resume

Abort

Transfer function




*T0=21/01/2024 03:24:41

*Avg=5

*BW=0.046875

Transfer function




*T0=21/01/2024 03:24:41

*Avg=5

*BW=0.046875

Coherence



*T0=21/01/2024 03:24:41

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume


Abort

Repeat

Fourier tools

done

Transfer function




*T0=21/01/2024 03:27:40

*Avg=5

*BW=0.046875

Transfer function




*T0=21/01/2024 03:27:40

*Avg=5

*BW=0.046875

Coherence



*T0=08/06/2018 18:30:05

Avg=10

BW=0.0234375

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume

Abort


Repeat

Fourier tools

done

Transfer function

Magnitude




*T0=21/01/2024 03:31:34

*Avg=5

*BW=0.046875

Transfer function

Phase (deg)




*T0=21/01/2024 03:31:34

*Avg=5

*BW=0.046875

Coherence

Coherence



*T0=21/01/2024 03:31:34

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume

Abort

Repeat

Fourier tools

done