


Transfer function




*T0=20/01/2024 20:14:15

*Avg=5

*BW=0.046875

Transfer function




*T0=20/01/2024 20:14:15

*Avg=5

*BW=0.046875

Coherence




*T0=20/01/2024 20:14:15

*Avg=5

*BW=0.046875

Transfer function



*T0=20/01/2024 20:14:15

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume


Abort

Repeat

Fourier tools


done

Transfer function




*T0=20/01/2024 20:17:54 *Avg=5 *BW=0.046875

Transfer function




*T0=20/01/2024 20:17:54 *Avg=5 *BW=0.046875

Coherence



*T0=20/01/2024 20:17:54 *Avg=5 *BW=0.046875

Transfer function



*T0=20/01/2024 20:17:54 *Avg=5 *BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause


Resume

Abort

Repeat

Fourier tools

Transfer function




*T0=20/01/2024 20:21:03

*Avg=5

*BW=0.046875

Coherence



*T0=20/01/2024 20:21:03

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume

Abort

Reset

Fourier tools

done