


Transfer function




*T0=21/01/2024 02:36:08

*Avg=5

*BW=0.046875

Coherence



*T0=21/01/2024 02:36:08

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...


Print...

Pause

Resume

Abort

Transfer function




*T0=21/01/2024 02:39:51

*Avg=5

*BW=0.046875

Coherence



*T0=21/01/2024 02:39:51

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...


Print...

Pause

Resume

Abort

Transfer function




*T0=21/01/2024 02:42:54

*Avg=5

*BW=0.046875

Coherence



*T0=21/01/2024 02:42:54

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume

Abort

Repeat

Fourier tools

done