


Non linear vibration coupling is not at the PSL table or input mode cleaner tube


PSL table shaker

Jitter coupling only. The sweep line in strain is only as wide as the sweep line in the accelerometers because it couples only linearly.


Strain



PSL
table
accel.






MC
tube
accel.



Global acoustic

The sweep line in strain is widened, relative to the line in the accelerometers, by non-linear coupling.



Input MC tube shaker

Much weaker coupling indicates that the coupling site is not the MC tube.

