




Input Measurement Excitation Result



Reset

Zoom

Active

New

Options...

Import...

Export...

Reference...

Calibration...



Print...


Start






Pause

Resume


Abort







Transfer function




*T0=29/06/2026 21:12:08

*Avg=3

*BW=0.0234375

Coherence




*T0=29/06/2026 21:12:08

*Avg=3

*BW=0.0234375

Transfer function




*T0=29/06/2026 21:12:08

*Avg=3

*BW=0.0234375

Transfer function



*T0=29/06/2026 21:12:08

*Avg=3

*BW=0.0234375

Reset

Zoom

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Start

Pause

Resume

Abort

