


Transfer function




*T0=12/08/2026 20:26:44

*Avg=4

*BW=0.0234375

Transfer function




*T0=12/08/2026 20:26:44

*Avg=4

*BW=0.0234375

Coherence




*T0=12/08/2026 20:26:44

*Avg=4

*BW=0.0234375

Transfer function



*T0=12/08/2026 20:26:44

*Avg=4

*BW=0.0234375

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume


Abort

Repeat

Fourier tools


running

Transfer function




*T0=12/08/2026 20:31:05 *Avg=3 *BW=0.0234375

Coherence




*T0=12/08/2026 20:31:05 *Avg=3 *BW=0.0234375

Transfer function



*T0=12/08/2026 20:31:05 *Avg=3 *BW=0.0234375

Transfer function



*T0=12/08/2026 20:31:05 *Avg=3 *BW=0.0234375

