


Transfer function




*T0=12/08/2026 20:50:25

*Avg=5

*BW=0.0234375

Transfer function




*T0=12/08/2026 20:50:25

*Avg=5

*BW=0.0234375

Coherence




*T0=12/08/2026 20:50:25

*Avg=5

*BW=0.0234375

Transfer function



*T0=12/08/2026 20:50:25

*Avg=5

*BW=0.0234375

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume


Abort

Repeat

Fourier tools


done

Transfer function




*T0=12/08/2026 20:55:35 *Avg=4 *BW=0.0234375

Coherence




*T0=12/08/2026 20:55:35 *Avg=4 *BW=0.0234375

Transfer function




*T0=12/08/2026 20:55:35 *Avg=4 *BW=0.0234375

Transfer function



*T0=12/08/2026 20:55:35 *Avg=4 *BW=0.0234375

Transfer function




*T0=12/08/2026 20:59:25

*Avg=4

*BW=0.0234375

Coherence



*T0=04/03/2024 18:30:19

*Avg=5

*BW=0.046875

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume

Abort

Repeat

Fourier tools

running