


Transfer function




*T0=12/08/2026 21:03:55

*Avg=4

*BW=0.0234375

Coherence



*T0=14/07/2026 19:27:34

*Avg=5

*BW=0.0234375

Active New Options... Import... Export... Reference... Calibration... Print...

Pause

Resume


Abort

Repeat

Fourier tools

running

Transfer function




*T0=12/08/2026 21:07:58

*Avg=4

*BW=0.0234375

Coherence



*T0=17/07/2026 16:53:21

*Avg=5

*BW=0.0234375

Active

New

Options...

Import...

Export...

Reference...

Calibration...

Print...

Pause

Resume


Abort

Repeat

Fourier tools

running

Transfer function




*T0=12/08/2026 21:11:52

*Avg=4

*BW=0.0234375

Coherence



*T0=12/08/2026 21:11:52

*Avg=4

*BW=0.0234375

Active New Options... Import... Export... Reference... Calibration... Print...

Pause

Resume

Abort