



TOP MASS



Transfer function




T0=16/04/2014 22:42:12

Avg=5

BW=0.0117187

Coherence




T0=16/04/2014 22:42:12

Avg=5

BW=0.0117187

Transfer function




T0=16/04/2014 22:57:07

Avg=7

BW=0.0117187

Coherence



T0=16/04/2014 22:57:07

Avg=7

BW=0.0117187

Reset Zoom Active New Options... Import... Export... Reference... Calibration... Print...


Start

Pause


Resume

Abort


L1 (UIM)





Transfer function



Coherence





L2 (PUM)

