


Vibration Absorber S/N 41 – Parallel to Accelerometer:

Tap test on the vibrational absorber itself.



Vibration Absorber S/N 41 – Perpendicular to Accelerometer:

Tap test on the vibrational absorber itself.

