




L1 Actuation Magnitude Weighted Mean



L1 Magnitude Meas/Fit Residual -- Fit: Zero Pair = 9.00 * Exp(+i * pi/180 * 52.00) [Hz]



L1 Actuation Phase Weighted Mean



L1 Phase Meas/Fit Residual -- Fit: Delay = 39.200000 [us]

