

22-HWS Power 21A-HWS Temp Sensor 21B-HWS Position X-axis	31-HWS In from Oiled motor on top of table	23-HWS Sled X 24-HWS 25-HWS Sled Y 26-HWS	Cables, no Feed thru Orange Orange Grey Grey 10 Power Rack ±18V 10 Polarization uniting field (back inside enclosure)	REM Panel All Empty
17-HWS Filter 18-HWS Filter				


D1200934

D1100323

D1200614

No Panel

TCS sled driver powered off.



All cameras set to 14V.

Pico meter

Front Panel



31-4105



Empty

Pico meter

Rear Panel



3003

Power



Pico meter

002



Pico meter

001