
27 Feb 2019 R. Abbott S1900052, D1101176

6,25 MHZ LHO SQUEEZER CLF Photodetector



Electrolytic

1 Juf 50V

Cop as replacement

for CZZ tantalum

found damaged

from inrush

Current (Hotswap

related maybe)