




I believe this pattern is either visible light, or a product of PRM being misaligned during this image. However, the Forward Rejected Beam is missing ROM RH11 in this image, as it is in the IR images.