


Mitchell loosening set screws in the support ring



New hardware in place



Corey and Mitchell checking new ring position with plumb bob



10 degree baffle!