


Injection must be five times higher after EX cryobaffle damping to produce similar DARM noise

DARM

Colors coordinated with accelerometer traces



*T0=28/03/2024 20:25:00

*Avg=30/Bin=2


BW=0.1875

Accelerometer

Accelerometer

Showing 3-5 Hz shaker injections. The orange trace is before damping, all others, after damping.

Two lowest-level traces: no shaker injection and best fan running.



*T0=28/03/2024 17:19:44

*Avg=30/Bin=2

BW=0.1875