


One of the two Beamsplitter 45 degree annular beams, the one with the cone axis in the +Y, -X direction, travels down the center of the Y-arm and may be reflected by the BSC1-BSC8 reduction flange. This may explain why the flange motion can be consistent with beating shaker noise in DARM



View from -X, +Y  
viewport on ITMY  
chamber

This beam may reflect from the  
reduction flange between BSC1  
and BSC8 (old H2 chamber)