



BSC-8 Manifold Detritus Survey 24 August 2011



Above: Items removed from north beamtube bellows



Above: Items removed or wiped from east beamtube bellows, manifold “drop off” and manifold proper