



DARM, RED: acoustic noise injection, 1000-10000 Hz, BLUE: no injection



*T0=06/01/1980 00:00:00 *Avg=1

*BW=0

Accerometer. near suspension, taps on ISI suspension wire loc. 3, BLUE: damping clamp on wire, RED: no clamp, all blue traces in front of red



*T0=06/01/1980 00:00:00

*Avg=1/Bin=10

*BW=0