




# Vertical GS13s shipment #3523


Presence of oxide residues











SOUTH

