

#### Shift Activities

- 8:14 Contractor Ken parking near Mechanical Room (prepping for HVAC Piping for Bubba...hammer drill work possibly later--will notify Control Room).
- 8:47 Overhead Door contractor for LSB work (Bubba)
- 8:51-9:36 ITMx Stage2 coil driver check (Hugh)
- 8:52 HAM4 RGA bakeout check (Chandra)
- 9:05 ETMx & ETMy Charge measurements (Betsy)
- 9:10-11:35 PSL Work (King, Bartlett, Oberling)
- 9:35-9:44 High Voltage interlock for ITMs check (Ed)
- 9:43 Visual of VAC equipment at EX (Gerardo, Chandra)
- 10:02-10:43 Installing hardware for PCal Shelf (Travis)
- 10:03 **TRANSITIONED BRS to VERY WINDY!, due to Gerardo/Chandra/Travis' visit to End Stations**
- 10:50 Loading up Boom Lift at EX (Bubba, John)
- 10:57 Retrieving EX anemometers (Warner)
- 10:59 Pallet rack/3ifo check (Betsy, Mitch)
- 12:34 Received Emergency Alarm Testing phone call
- 3:20 CP3 Overfill (Chandra)