



ISCT6 On-table Fibre for Pump:



Fibre coupler end:



Clean enough.

Patch panel end:

Before cleaning:




Some dirt and chemical left?

After cleaning:



6m Long Green Fibre:



Patch panel end:



Good Enough, did little clean


Feedthroug End:

Before cleaning:



Some dirts.

After cleaning:



Red Fiber Feedthrough End:



Clean enough.

7/31/2018