






Shaking of BSC2 wall

Impulse



Shaking of manifold reduction flange near ITMX optical lever

Power spectrum




*T0=19/04/2019 22:21:42

*Avg=1

BW=0.187499

Power spectrum



*T0=19/04/2019 22:51:35

*Avg=20/Bin=11L

BW=0.187499