




### Good vs. Broken SR785




### Freq. Resp. Measurements



### of a random D0902783-style



### AA Chassis Channel



created by quick\_plot\_SR785woes\_20240530 on 31-May-2024, J. Kissel