

End Station: X-End Date: 24-06-11
 Beam Movement Performed By: F. Lids
 Beam moved: Inner Outer
 Previous move: Center Current move: Left

Rx voltage values between steps		
Step	Local time	Voltage (V)
Initial	11 00	3.384
1	11 40	2.834
2	11 43	1.496
:	11 47	1.496
:	12 00	1.520
3	12 05	1.582
:	12 11 12 11	1.579
4	12 15	2.885
→ 8	12 25	3.384

Final

Notes:

From step (2) } Fine adjustments in pitch did not change signal.
 Adjustments in yaw increased signal. Recording 11:54 ^(local) ~~(UTC)~~
 ↳ by moving clockwise on screw (left)

step (3) Have not optimized pitch yet. Value significantly higher than any other inner beam configurations before.

Adjusting pitch did not improve signal.